



## JobTrack (İş Takibi) Sistem Gereksinimleri

Bu döküman versiyon 18 ve daha yüksek **JobTrack** sistem gereksinimlerini listeler.

**JobTrack** bir iş istasyonuna kurulmadan önce bu gereksinimlerin uygunluğundan emin olunuz.

**JobTrack** SQL modunda cncKad sunucusu (**Metalix** Uygulama Sunucusu) üzerinden çalışmayı gerektirir.

CncKad sunucusu için belirlenen ana bilgisayar bir Window Active Directory domain parçası olması gerekir. **Metalix** uygulamaları için (**cncKad**, **MBend**, ve **CAD Link**) yapılandırılmış tüm ana bilgisayarlar SQL modunda çalışmalıdır.

### İşletim Sistemi

Gerekli	Önerilen
Microsoft® Windows® "Home" sürümü desteklenmemekte	64-bit Microsoft® Windows® 10 Pro

### Hardware

Gerekli	Önerilen
Processor (CPU) Type Apple Mac® desteklenmemekte	Intel® Xeon® E3 or Core i7, 3.30GHz or faster
Hafıza (RAM)	20 GB
Hard disk (available space)	500 GB
Monitor çözünürlük	1920 x 1080
USB port for HASP key (dongle)	Port on motherboard

### Yazılım

Functionality	Önerilen
<b>Gerekli</b> – Microsoft .NET Framework	4.5.2
<b>Gerekli</b>	<ul style="list-style-type: none"><li>Microsoft Windows networking</li><li>Installed Windows edition: Pro \ Business \ Ultimate</li><li>Microsoft Internet Explorer® 8 or higher</li></ul>
<b>Gerekli</b> – 64 bit Microsoft® Office	Full 64 bit Microsoft® Office packet 2013 including Word, Excel, and Access Non-Microsoft® Office packets desteklenmemkte
<b>Gerekli</b>	Adobe® Flash® Player 15
<b>Gerekli</b>	An on-site network/system administrator (even part time) with administrative access to the domain and responsibility for SQL Server backup.
<b>Gerekli</b> – Windows Active Directory	All hosts configured for Metalix applications (cncKad, MBend, and CAD Link) operating in SQL mode should be part of the same domain Domain controller machine (PDC or BDC) desteklenmemkte